

INSTRUCTIONS and PARTS




**ATLAS**

CLAUSING CORPORATION  
KALAMAZOO, MICHIGAN 49007


**NO. 618  
6" ATLAS BACK GEARED  
SCREW CUTTING LATHE**

**NO. 12A, 16A  
ARMATURE LATHE**

JULY, 1976



NO. 618  
BENCH LATHE



NO. 12A, 16A  
ARMATURE LATHE

# 618 ATLAS 6" BACK GEARED SCREW CUTTING LATHE and 12A, 16A ARMATURE LATHE

## INSTRUCTIONS FOR ORDERING REPAIR PARTS

---

IT IS **IMPORTANT** TO FURNISH THE FOLLOWING INFORMATION IN ADDITION TO QUANTITY REQUIRED:

1. PART NUMBER
2. PART NAME
3. MODEL and SERIAL NUMBER of machine tool-you'll find both on the metal plate attached to machine.

ORDER REPAIR PARTS  
FROM  
CLAUSING SERVICE CENTER  
811 EISENHOWER DRIVE, SOUTH  
GOSHEN, INDIANA 46526

## TABLE OF CONTENTS FOR LATHE PARTS

---

UNIT ASSEMBLIES .....	3
CARRIAGE and COMPOUND .....	4-5
HEADSTOCK .....	6
LEAD SCREW, CHANGE GEARS, GEAR GUARD and LATHE BED .....	7
COUNTERSHAFT and TAILSTOCK .....	8



# INSTRUCTIONS

## NO. 6L-1 SIX INCH LATHE MOUNTING

JAN. 1969

FILE NO. 6L-1




Figure 1

### MOUNTING LATHE

Place lathe on bench in approximately position shown in figure 1. Bench top should be at least 20 by 34 inches. Front edges of legs should be about  $\frac{3}{4}$ " from front of bench top. Mark positions of four holes in lathe legs and drill holes to accommodate either lag screws or bolts as desired.

Next, bolt lathe to bench top and level bed by carefully following instructions contained in bulletin "PROPERLY LEVEL THE LATHE BED". This is a most important step and should not be slighted.




Figure 2

### MOUNTING COUNTERSHAFT

The four holes for the countershaft bracket may now be located and drilled by following the dimensions in figure 1. With countershaft belt tension screws (refer to figure 2), in about the midway position, place spindle belt on smallest step of countershaft pulley and largest step of spindle pulley. Bolt countershaft bracket lightly to bench.

Put rocker lever in tension position, that is, so that the belt tension screws (refer to figure 2) rest on the smaller of the two flat spots on rocker shaft. Now move countershaft bracket on its slotted holes so that countershaft spindle is parallel with lathe spindle. Move bracket away from lathe until belt is tight and tighten the four mounting bolts. With belt tension screws, adjust belt so that with a moderate amount of pressure belt can be depressed about 1" in the center. Lock this adjustment by tightening locknuts on belt tension screws.

### MOUNTING MOTOR

Before mounting motor, make all electrical connections.


Slide pulley on motor shaft so that small step is toward motor. Place motor in position shown in figure 2, with belt on small step of motor pulley and on large step of countershaft pulley. Be sure rockershaft is still in tension position and pull motor as close to countershaft bracket as belt will allow, line up belt and bolt motor to bench. Check tension and alignment of both belts, then tighten all mounting screws or bolts securely.

# INSTRUCTIONS

## NO. 6L-2 GEAR CLEARANCE

JAN. 1969

FILE NO. 6L-2



View of two meshing gears showing gear clearance.

When setting up gear train, sufficient clearance must be allowed between two meshing gears. Gear clearance does not reduce accuracy of a thread cutting operation because all play, or back lash, is taken up in one direction.

### A SUGGESTED METHOD TO OBTAIN PROPER GEAR CLEARANCE IS:

1. Place a sheet of thick wrapping paper between the teeth of two meshing gears.
2. Tighten gears in position.
3. Remove paper.

Clean gears occasionally to remove any chips which become lodged in gear teeth. Chips in gear teeth result in inaccuracies when cutting screw threads. A wad of cloth placed in the rear end of spindle will prevent chips from working into gear teeth.

### LUBRICATION

A small amount of S.A.E. No. 30 oil or grease (we recommend Keystone No. 122 Gear Lubricant or equivalent) applied to gear teeth, will aid in obtaining smoother, more quiet operation.

*NOTE: Remove oil and dirt before applying grease.*






FIGURE 1, Positions for checking level readings.

## LATHE BENCH REQUIREMENTS

1. A rigid bench or floor stand must be used for mounting the lathe. Bench top must have a clear semi-hard or hardwood top at least 1-5/8" thick, cleated or well doweled to form a rigid table. Do not use soft-woods or boards not cleated together.
2. Bench legs should be of heavy construction, preferably 4" x 4" lumber, well braced and securely anchored to bench top. Provide legs with lugs for bolting bench securely to floor. Overall height of bench should be approximately 30 or 32 inches.
- 3: Level the floor stand or bench before mounting lathe, this will omit excessive shimming when leveling lathe bed. Use a precision machinists level, placing shims as required between bench legs and floor to accurately level bench top. BOLT BENCH TO FLOOR.
4. Mount the lathe on the floor stand or bench. If bench is used, mark and drill four 3/8" diameter holes in bench top under corresponding holes in lathe legs. Do not bolt lathe securely in position.

## HOW TO LEVEL THE LATHE BED

1. Using only a precision machinists spirit level, check level readings at the positions shown in Figure 1 above. A VERY SENSITIVE LEVEL MUST BE USED. A sensitive level should move the bubble approximately 1/8" when a .003" shim is placed under one end of lathe.
2. Level readings in the four positions must be identical. Compensate variations of bubble readings with thin metal shims placed around bolts between lathe legs and bench top until bubble readings are identical. See Figure 2 for approximate size of shim.
3. Shim should be the only contact point with the bench top. If outer or inner edges of bench legs bear on bench top, bed is apt to be bowed or twisted when lathe is bolted down.
4. Bolt lathe securely in position and recheck level readings. Variations in bolt pressure may twist the lathe bed out of level.
5. The levelness of the lathe should be inspected at frequent intervals, especially before and after machining heavy work.




FIG. 2. Approximate shim dimension.

IF SATISFACTORY PERFORMANCE IS NOT OBTAINED OR OPERATING INACCURACIES OCCUR — CHECK THE LATHE BED AND MAKE SURE IT IS PERFECTLY LEVEL.



# LUBRICATION CHART

## FOR ATLAS 6" LATHE



### IMPORTANT — LUBRICATE LATHE BEFORE OPERATING

#### CODE

- A — OIL DAILY with S.A.E. No. 20 oil
- B — OIL WEEKLY with S.A.E. No. 20 oil
- C — OIL MONTHLY with S.A.E. No. 20 oil

#### CARRIAGE — HEADSTOCK AND BACK GEARS

\*Remove screw to oil bearings.

D — KEEP CLEAN and well oiled at all times.

E — LUBRICATE gear teeth with Keystone No. 122 gear lubricant, or equivalent, to obtain smoother, more quiet operation. Remove oil and dirt before applying grease.

#### TAILSTOCK — LEADSCREW — LEADSCREW BEARING — RACK

\*\*About once a month clean with kerosene and a brush, then cover with oil.


### KEEP YOUR LATHE CLEAN

Oil and dirt form an abrasive compound which can easily damage carefully fitted bearing surfaces. Wipe the bed and all polished parts with a clean oily rag at frequent intervals. Use a brush to clean spindle threads, gear teeth, lead screw threads, etc.

### SPEED CHART

COUNTERSHAFT

SPINDLE



#### SPINDLE SPEEDS IN R.P.M.

DIRECT DRIVE			BACK GEAR DRIVE		
Spindle Belt Position	Motor Belt Position		Spindle Belt Position	Motor Belt Position	
	A	B		A	B
1	380	975	1	55	145
2	540	1380	2	82	210
3	835	2150	3	125	315
4	1185	3050	4	185	463

ATLAS PRESS COMPANY • KALAMAZOO, MICH., U.S.A.



CLAUSING CORPORATION  
KALAMAZOO, MICHIGAN 49007

# WIRING INSTRUCTIONS

for  
SINGLE PHASE MOTORS

Manufactured by  
Howell Electric Motors Co.


JULY, 1976

1. Make all wiring connections before mounting motor.
2. Run both line and switch cords through the TOP knock-out in the terminal box (see diagram below).
3. Motor must rotate counterclockwise when viewed from the end of the motor opposite the shaft -- diagram below shows correct hook-up for either 110V or 220 V current.

MOTOR NO.	CATALOG NO.	DESCRIPTION
38-J11-4100-2	2720	1/2 HP - 1-phase - 115/230 volts - 1725 RPM - 7/3.5 AMPS.
38-J3-3100-2	2730	1/3 HP - 1-phase - 115/230 volts - 1725 RPM - 5.6/2.8 AMPS.
38-J11-5100-1	2790	3/4 HP - 1-phase - 115/230 volts - 1725 RPM - 9.6/4.8 AMPS.

Made by Howell Electric Motors Company.

This wiring diagram applies only to motors listed above.




NOTE: TO REVERSE ROTATION OF MOTOR INTERCHANGE RED LEAD WITH BLACK LEAD.  
To wire other make motors follow manufacturer's instructions.



# LUBRICATION CHART

## FOR ATLAS 6" LATHE



### IMPORTANT — LUBRICATE LATHE BEFORE OPERATING

#### CODE

- A — OIL DAILY with S.A.E. No. 20 oil
- B — OIL WEEKLY with S.A.E. No. 20 oil
- C — OIL MONTHLY with S.A.E. No. 20 oil

#### CARRIAGE — HEADSTOCK AND BACK GEARS

\*Remove screw to oil bearings.

D — KEEP CLEAN and well oiled at all times.

E — LUBRICATE gear teeth with Keystone No. 122 gear lubricant, or equivalent, to obtain smoother, more quiet operation. Remove oil and dirt before applying grease.


#### TAILSTOCK — LEADSCREW — LEADSCREW BEARING — RACK

\*\*About once a month clean with kerosene and a brush, then cover with oil.

### KEEP YOUR LATHE CLEAN

Oil and dirt form an abrasive compound which can easily damage carefully fitted bearing surfaces. Wipe the bed and all polished parts with a clean oily rag at frequent intervals. Use a brush to clean spindle threads, gear teeth, lead screw threads, etc.

### SPEED CHART



#### SPINDLE SPEEDS IN R.P.M.

DIRECT DRIVE			BACK GEAR DRIVE		
Spindle Belt Position	Motor Belt Position		Spindle Belt Position	Motor Belt Position	
	A	B		A	B
1	380	975	1	55	145
2	540	1380	2	82	210
3	835	2150	3	125	315
4	1185	3050	4	185	463


ATLAS PRESS COMPANY • KALAMAZOO, MICH., U.S.A.




# Atlas 6" LATHE UNIT ASSEMBLIES





M6-2X HEADSTOCK  
ASSEMBLY  
SEE PAGE 6




M6-208X COUNTERSHAFT  
ASSEMBLY  
SEE PAGE 8



M6-9XY CARRIAGE ASSEMBLY  
SEE PAGE 4 and 5




M6-28X GEAR GUARD  
ASSEMBLY  
SEE PAGE 7



3950-24 TAILSTOCK ASSEMBLY  
SEE PAGE 8



L9-35X LEAD SCREW AND  
FEED GEAR ASSEMBLY  
SEE PAGE 7



L9-IX BED, LEGS, AND  
RACK ASSEMBLY  
SEE PAGE 7

# CARRIAGE PARTS LIST

M6-115  
WRENCH



9-41  
ROCKER

M6-148  
SCREW




M6-40  
WASHER

M6-39  
POST, TOOL



M6-136  
ANCHOR

## M6-39X TOOL POST ASSEMBLY LESS WRENCH



## M6-9XY CARRIAGE ASSEMBLY

3/8-32 x 3/16  
HD'LESS SET SCREW  
(CUP PT.)

1/16 x 3/8 GROOVE  
PIN

No. 1 WOODRUFF  
KEY

W30-16  
OILER

M6-303  
SLIDE, COMPOUND REST  
TOOL POST  
W/OILER

10-24 x 1/2" RD. HEAD  
MACH. SCR. (2 REQD.)

M6-104  
HANDLE (2 REQD.)

M6-311  
COLLAR

3950-19  
SCREW WITH COLLAR

345-076  
GIB

8-32 x 7/16" HD'LESS SET  
SCR. (DOG PT.) 4 REQD.  
M6-223 NUT,  
GIB LOCK (4 REQ'D)

M6-263  
NUT

1/4"-20 HEX JAM  
NUT

M6-48  
COLLAR,  
GRADUATED

M6-306  
NUT

M6-302  
SWIVEL, TOOL POST

10-24 x 1/2" FLAT HEAD  
MACH. SCREW

M6-308  
CRANK, COMPOUND  
REST BALL

1/4"-20 x 1/2" ALLEN  
SET SCREW

M6-309  
PIN (2 REQD.)

M6-301  
SWIVEL, COMPOUND REST

M6-56  
GIB

342-148  
GUARD

10-32 x 3/4" HD'LESS  
SET SCR. (DOG PT.) 2 REQD.

10-226  
NUT (3 REQD.)


M6-19A  
NUT

10-32 x 3/4" HD'LESS SET  
SCR. (DOG PT.)

## 3950-27 COMPOUND REST ASSEMBLY




## CARRIAGE PARTS LIST



**M6-9X CARRIAGE ASSEMBLY**  
LESS COMPOUND REST AND THREADING DIAL







# HEADSTOCK PARTS LIST









## LEAD SCREW, CHANGE GEARS, GEAR GUARD, AND LATHE BED PARTS LIST





## COUNTERSHAFT AND TAILSTOCK PARTS LIST







CLAUSING CORPORATION  
KALAMAZOO, MICHIGAN 49007

# THREADING CHART

for  
6" ATLAS LATHES

JULY, 1976

**FIG. 1**

SET-UP FOR  
8-16 THREADS

## THREADING CHART

A-B-C ARE GEAR STUD POSITIONS  
B=BACK POSITION (TOWARD HEADSTOCK)  
F=FRONT POSITION (AWAY FROM HEADSTOCK)  
I=IDLER GEAR                   —=BLANK  
S=SPACER GEAR               XXS=STEEL SPACER

THREADS PER INCH	GEAR ON SCREW	POSITION C		POSITION B		POSITION A		SPINDLE STUD GEAR	FIG.
		B	F	B	F	B	F		
8	32F	32	64	—	—	64I	XXS	32	1
9	36F	32	64	—	—	64I	XXS	32	1
10	40F	32	64	—	—	64I	XXS	32	1
11	44F	20	40	—	—	64I	XXS	32	1
11.5	46F	20	40	—	—	64I	XXS	32	1
12	48F	20	40	—	—	64I	XXS	32	1
13	52F	20	40	—	—	64I	XXS	32	1
14	56F	20	40	—	—	64I	XXS	32	1
16	64F	20	40	—	—	64I	XXS	32	1
18	36B	—	—	64I	XXS	—	—	32	2
20	40B	—	—	64I	XXS	—	—	32	2
22	44B	—	—	64I	XXS	—	—	32	2
24	48B	—	—	64I	XXS	—	—	32	2
27	54B	—	—	64I	XXS	—	—	32	2
28	56B	—	—	64I	XXS	—	—	32	2
32	64B	—	—	64I	XXS	—	—	32	2
36	36F	20S	32I	—	—	XXS	64I	16	3
40	40F	20S	32I	—	—	XXS	64I	16	3
44	44F	20S	32I	—	—	XXS	64I	16	3
48	48F	20S	32I	—	—	XXS	64I	16	3
56	56F	20S	32I	—	—	XXS	64I	16	3
64	64F	20S	32I	—	—	XXS	64I	16	3
72	36B	56I	XXS	—	—	32	64	16	4
80	40B	56I	XXS	—	—	32	64	16	4
96	48B	56I	XXS	—	—	32	64	16	4
<b>FEED PER REVOLUTION OF SPINDLE</b>									
.0024"	64F	64	20	—	—	24	48	16	5
.0039"	64F	64	32	—	—	24	48	16	5
.0048"	64B	20	64	—	—	48	24	32	6
.0078"	64B	32	64	—	—	48	24	32	6

**FIG. 2**

SET-UP FOR  
18-32 THREADS

**FIG. 3**

SET-UP FOR  
36-64 THREADS

**FIG. 4**

SET-UP FOR  
72-96 THREADS

**FIG. 5**

SET-UP FOR  
.0039" FEED

**FIG. 6**

SET-UP FOR  
.0048" FEED