
SIMONET + CO. LTD MACHINE TOOL WORKS 4500 SOLEURE (SWITZERLAND)

SIMONET



Precision screw cutting lathe

DZ-450



Precision screw cutting lathe

DZ-450

length/breadth/height

Simonet lathes - built on the unit construction principle

DC-102 tool maker's lathe DZ-450 screw cutting lathe

These two types are mainly intended for the precision machining of single parts or small batches of parts. They ensure a wide field of application: tool room, laboratory, repair shop, assembly shop.

Production runs and second-setting machining are performed on the

DR-102 capstan lathe DDA-102 semi-automatic second-operation lathe **DRA-102** automatic capstan

lathe

camless

Universal interchangeability of the units (headstocks, crosswise arranged slides, etc.) and a large number of accessories and attachments (clamping elements, grinding and milling attachments, etc.) are the distinguishing features of these precision machines. Thus they can be quickly adapted to deal economically with various kinds of workpieces.

On these lathes small-sized parts can be machined to a high degree of accuracy. The automatic types permit high rate production.


Specifications

Screw cutting lathe DZ-450

Height of centres			4"
Distance between centres			18"
Swing over slide			51/8"
Headstock with reduction gear			1:5
Collets W 20: Shank diameter			20 mm
Range of diameters passing three	ough shank		1/32" to 9/16"
Range of diameters not passing	through shank		5/8" to 3/4"
Fine feed reduction gear			1:4
Thread pitches	Number 29	British threads/1"	5 to 112
	Number 24	metric mm	0.05 to 4
Longitudinal feeds			.00075" to .05
Travel of longitudinal slide			43/4"
Travel of transverse slide			43/4"
Travel of tailstock sleeve			23/4"
Inner taper of tailstock sleeve			Morse 1
Spindle speeds		r.p.m.	14-2750
Weight with bench and drive			685 lbs




Space required with bench and drive



Semi-automatic second-operation lathe DDA-102



Tool maker's lathe DC-102




53" x 35" x 50"

Automatic capstan lathe DRA-102




Precision screw cutting lathe

DZ-450



214

Headstock with reduction gear (1:5) for collets W 20 shank dia. 20 mm, with special plain bearings for speeds up to 2500 r.p.m., gear running in oil bath




518

Lever-operated quick closing attachment, for collets type W 20, fits on headstock No. 214 with reduction gear and change gear box



150

Collets W 20, shank dia. 20 mm, range of dia. passing through 1/32-9/16", range of dia. not passing through 5/8-3/4"




142

Stop for adjustment of depth for collets W 20, maximum depth 2"



225

Chuck 4" dia., with shank W 20, and 6 jaws for internal gripping and 6 for external



155

Internal step collet blank 2" dia. without steps, shank W 20

156


Internal step collet blank 3" dia. without steps, shank W 20

157

Internal step collet blank 4" dia. without steps, shank W 20

158

Clamping cone for collets No. 155, 156 and 157



165

External step collet blank 2" dia. without steps, shank W 20

166

External step collet blank 3" dia. without steps, shank W 20

167

External step collet blank 4" dia. without steps, shank W 20

168

External step collet blank 5" dia. without steps, shank W 20



169


Closing cone for external step collet No. 165

170

Closing cone for external step collet No. 166

171

Closing cone for external step collets No.167 and 168



227

Three-jaw s. c. chuck, 4%" dia., fitted on backplate, with 3 turning and 3 drilling jaws

226

Four-jaw s.c. chuck, 4%" dia., fitted on backplate, with 4 turning and 4 drilling jaws




222

Permanent magnetic chuck 4" dia., fitted on backplate

223

Permanent magnetic chuck 6" dia., fitted on backplate




230

Face plate 7½" dia. with 4 T-slots and tapped holes, including 2 clamping dogs



Precision screw cutting lathe

DZ-450



510


Bed surface-hardened and ground, length 39", change gear box with fine feed reduction gear (ratio 1:4), pick-off gears, apron for thread cutting and turning, automatic disengagement, crosswise arranged slides



Fixed toolholder support for the back


272

Lever operated longitudinal slide, interchangeable, with 2 adjustable stops, slide travel 39/16"



274

Rear interchangeable slide, with screw for longitudinal movement, travel 2"



249

319


Base plate with graduation in degrees

250

Vertical slide, slide travel 4%"


252

Angle plate with 2 clamping surfaces 3½" x 3½"



251

Dividing head for vertical slide, for W 20 collets, incl. 3 indexing wheels with 48, 60 and 100 teeth



245

Milling head, with drawbar for W12 collets, cutter speeds 480-3000 r.p.m.

246

Cutter arbors 6, 8, 10 and 13 mm dia., shank type W 12

154

Collets W 12, shank dia. 12 mm, range of dia. passing through $^{1}/_{32}-^{5}/_{16}$ ", range of dia. not passing through $^{3}/_{8}-^{1}/_{2}$ "



Precision screw cutting lathe


DZ-450



290 Toolpost




291 Toolpost with 2 screws



288 Four-way tool post for tools %" x %"




283 Toolholder right-sided for tools %" x %"



285/111 Quick-change tool post, without toolholders



287 Simple block toolholder for tools 3/8" × 3/8"



284 Toolholder left-sided for tools %" x %"



285/131

285/131b



Toolholder for tools %" x %"



296 Set of 7 internal turning tools, of high-speed steel, with V-block



235

Grinding attachment running in adjustable precision taper roller bearings, can be regulated in height, with drawbar for B 8 collets, maximum spindle speed 20 000 r.p.m.

236

Insert for external grinding



Toolholder with prism for tools %" x %"

285/132 Double toolholder for tools %" x %"



294

Set of 12 external turning tools of high-speed steel

295

Set of 10 external turning tools tipped with carbide



153

Collets B 8, shank dia. 8 mm, range of dia. passing through $\frac{1}{32} - \frac{3}{16}$ ", range of dia. not passing through $\frac{13}{64} - \frac{5}{16}$ "




285/134 Cutting-off toolholder for tools %" x %"



Precision screw cutting lathe

DZ-450



218

Tailstock with Morse taper 1, travel of spindle sleeve 23/4", with 1/16" graduations along the spindle sleeve



100

Tailstock centre with Morse taper 1

102

Tailstock carbide centre with Morse taper 1



101

Half centre with Morse taper 1



103

Tailstock live centre with Morse taper 1



104

Hollow centre with Morse taper 1




105

Half hollow centre with Morse taper 1



106

Drilling fork with Morse taper 1




107

Half drilling fork with Morse taper 1



108

Drilling plate dia. 2" with Morse taper 1




110

Drill chuck with Morse taper 1, capacity 1/32" to 3/8"


111

Keyless drill chuck with Morse taper 1, capacity 1/32-3/8"



320

Lever operated tailstock with 4 adjustable stops, with collet drawbar for W 20 collets, travel of spindle sleeve 39/16"



322

Inclined tailstock turret head with W 20 shank for 4 tools with shanks 12 mm dia.

323


Inclined tailstock turret head with W 20 shank for 4 tools with shanks 20 mm dia.

335

Adaptor for No. 322


336

Adaptor for No. 323




321

Lever- and spring-operated tailstock, with Morse taper 2, travel 11/4"



182

Collet chuck for rubber-flex collets No. 183, fitted on backplate



183

Rubber-flex collets with steel collet jaws. Set comprising 10 collets for an infinitely variable capacity from 3/32" to 11/6", .1" range per collet




220

Hand rest



221

Rectangular table for hand rest 2%" x 4"



229

Fixed steady with 3 jaws, maximum opening 2"



TV-45

Electric individual drive with geared reduction drive for speeds 1:1 and 1:6, toothed wheels hardened and ground running in oil bath

Individual drive	TV-45	Headstock speeds						
Motor:		Headstock with reduction gear W 20 Item 21						
Speeds r.p.m.* Output HP	Item No.	Number of steps	r.p.m.					
1500	410	12	14-1380					
0.8	417	12	22-2080					
3000 1.1	412	12	28–2750					
1500/3000 0.75/1.1	411	. 24	14–2750					



440

Hand switch in mounting casing, for running in both directions, for single-speed motors

441

Hand switch in mounting casing, for running in both directions, for two-speed motors




442

Hand switch with motor protection switch, in mounting casing, for running in both directions, for single-speed motors

445

Hand switch with motor protection switch, in mounting casing, for running in both directions, for two-speed motors




465

Cord pulley, normal dia. 7"/3¾"/2¼", for grinding attachment 5000–18800 r.p.m. (motor 3000 r.p.m.)

466

Cord pulley dia. 10"/7"/3¾", for grinding attachment 5000-26000 r.p.m. (motor 3000 r.p.m.)



421

Guard for flat belt between individual drive and headstock




Precision screw cutting lathe

DZ-450



610

Box-form bench of sheet steel, with 3 swivelling tool drawers, 1 tool shelf, central lock for drawers and shelf, bench top 251/2" × 47", height 34"




615

Swarf tray with drain pipe

620


Coolant equipment with tank (capacity 6½ gal.) electrically-driven pump with built-on switch (delivery 8 gal./min.), including fittings



625

Lighting fitting with switch and 3-pole plug








Horizontal jig boring mill

Assembly shop



BRUNNER MACHINE TOOLS LTD. 241-7 HIGH STREET, ACTON, LONDON, W.3. Tel. 01-992 6011.

Working Instructions DZ-450 Screw cutting lathe

TRANSPORT

For the transport, the machine remains completely assembled together. The cross slide is clamped to the bed by means of the clamping eccentric 12, which is located behind on the cross-slide guide. When receiving the machine, clean all grease-covered parts with a cloth soaked in kerosene.

ACCURACY OF THE MACHINE

Before leaving our works, the lathe is tested with regard to accuracy in accordance with the accompanying test report. It has no error greater than the values permitted according to Prof. G. Schlesinger's "Testbook for Machine Tools". This accuracy, however, is to a large extent dependent on the accuracy with which the precisely scraped lathe-bed ist set up and levelled. (See sheet 2).

LUBRICATION

All lubricating spots indicated on the accompanying sheet No. 16 have to be lubricated periodically with the prescribed lubricants.



SIMONET & CO. A.G. SOLOTHURN


SCHWEIZ


Geschr. 25.5.56 7000 Gepr.

Nr. PD-50-84 Sheet No.

Leitspindeldrehbank DZ-450

Transport mit Kran.





Geschr 1.9.69 Pel Gepr

PD-50-606/2

Blatt

SIMONET & CO. A.G. SOLOTHURN SCHWEIZ

Bench lathes DC-102 DD-102 DR-102 DZ-450

SETTING UP THE MACHINE

The lathe must be set up or erected in such a way that no twisting stresses can be caused in the lower part or in the bed.

Check and level the bed accurately longitudinally and transversely by means of a precision spitit level.

If any errors are found when checking, proceed as follows:

a) Lathe mounted on box stand, item No. 610

Loosen the four locknuts of the through-going fixing screws B. Re-adjust and level with these four fixing screws B. Tighten moderately the locknuts of the four fixing screws B.

The alignment of the centres must be checked with a checking arbor and a dial gauge. Preferably, first overhung in the headstock, and then between the centres.


b) Lathe fixed on a workbench (wooden bench)

Fix the two cast-iron fixing plates onto the bench from below with the four wood screws D. After inserting two bushes E which must agree with the thickness of the bench, place the bed in position, and fix it moderately with the two fixing screws A. The highest point on left-hand and right-hand bush E is designated by a punch mark and must point outwards. Then accurately set and level the bed longitudinally and transversely with the four fixing screws B.

All four screws B must then take part in the fixing.

Tighten moderately the locknuts of the four fixing screws B.

The alignment of the centres must be checked with a checking arbor and a dial gauge. Preferably, first overhung in the headstock, and then between the centres.



F

niemais

anch

vervielfältigt, geteilt oder 2

zuganglich

iche Genehmigung durfen

SIMONET & CO. A. G. SOLOTHURN SCHWEIZ

Geschr. 28.9.71 HSLW Nr.
Gepr. PD-50-85

Blatt

Nr.

HEADSTOCK WITH REDUCTION GEAR, Item no. 214

The spindle can be locked in 12 positions by the rotary knob on the rear portion of the bearing. For very accurate dividing work, the eccentrically supported index pin is adopted. It has to be set onto the suitable circle of holes (48, 60, 100) and clamped with the set screw. For such dividing work, it is necessary to tighten the threaded pin 5 on the stepped pulley; in this way the pulley is connected direct with the spindle. In this case, the headstock reduction gear must of course remain disengaged.

By a light pull on the flat belt, the shifting operation of the gear can be facilitated. This shifting may only be done with the lathe at rest.

The two headstock bearings must be sufficiently lubricated periodically with a good mineral oil free from acids (viscosity about $3 - 4^{\circ}$ E at 50° C). The oil level in the reduction gear should not be higher than the middle of the inspection window.

The two ball bearings I with sealing discs are supplied filled with grease and do not require any attendance.

As gear oil we recommend the following makes: (In alphabetical order)


Caltex Oil	Regal AZ	2,9° E at 50° C
Esso Standard	Teresso 43	2,8° E at 50° C
5hell	Vitrea 27	3º E at 50° C
Vacuum Oil (Mobil Oil)	DTE light	2.80 E at 500 C

The re-adjusting of the bearings requires a certain amount of care and should only be carried out by men skilled in such work. The desired radial and axial play of the front bearing can be adjusted accurately by the threaded ring A, which is located behind the front taper bearing and is secured by two set screws, the bearing being touched up on the front face, if necessary. When doing so, take care that the contact surfaces remain strictly plane. The rear cylindrical bearing can be re-adjusted by tightening the threaded ring C on the side of the stepped pulley, and then at the same time the threaded ring E at the left must be loosened and possibly the insert in the bearing F may have to be re-machined.

ervielfältigt, eteilt oder Nr.

Maximum speed 2500 rpm.

Motor speeds in rpm.			
Initial speeds of the individual	drive in rp	m.	
Headstock speeds in rpm. Reduc	tion gear di	sengaged	N N
Headstock speeds in rpm. Reduc	tion gear en	gaged	



Dismantling

Remove cover K and unscrew threaded ring R. Screw out set screw 5 and loosen grub screw L until sleeve H is free to move on the spindle. Then the spindle together with the front bearing can be withdrawn to right.



SIMONET & CO. A.G. SOLOTHURN SCHWEIZ Geschr. 9.8.67 W.L.
Gepr.

PD-50-91A Blatt

Bench lathes DC-102, DR-102, DD-102, DZ-450.

CROSS SLIDE No. 216, 217 and 510

VERTICAL SLIDE No. 250


INTERCHANGEABLE LEVER-DPERATED SLIDE No. 272

SLOTTING ATTACHMENT No. 270

All slides can be taken to pieces quickly and easily. They should be thoroughly cleaned once a week and at the same time lubricated with a mineral oil free from acids and having a viscosity of $3-4^{\circ}$ E at 50° C. (Clean well behind the wedge guide, but do not lubricate).

By screwing out the conveying spindles or by loosening the flange of the lever-operated slide, the slide guideways are rendered easily accessible. The ball bearings of the feed screws are provided with a permanent grease packing and do not require any attention in service.

The play of the slide guides can be adjusted along the wedge guide by means of the threaded pins. In order not to stress the conveying spindles laterally, the bearing flange should be loosened and then screwed tight again in the foremost position. Any backlash appearing in the feed screw bearing can be taken up by means of adjusting collar A and the associated set screw. After having taken up backlash, check and make sure that the bearing runs free. The screw-nut A can be rendered accessible as follows: Take out the taper pin 5 and remove the crank, intermediate bush and dividing drum. If the conveying spindles and nuts have become much worn, these parts must be replaced by new ones. The same elements can be used for the longitudinal slide and the cross slide.






SCHWEIZ

17.11.67 U.W. Geschr. Gepr.

PD-50-97A

Blatt Nr.

Bench lathes DC-102 DR-102 DD-102 DZ-450



TAILSTOCK Item No. 218

The tailstock spindle sleeve can be screwed out completely for cleaning and for lubricating the bore as well as the traversing nut. Lubricate with non-acid mineral oil, viscosity at 50°C = 3 to 4°E.

The ball bearing of the traversing screw is provided with the so-called permanent lubrication and does not require any attention in service; the thrust needle bearing is delivered likewise with a "permanent" crease packing.

If the bearing has too much play, it can be taken up by tightening nut M. When doing this, the bearing should go on running free, i.e. when the tailstock spindle sleeve has been screwed out, the handle of the handwheel should bear downwards by reason of its own weight.

When, due to wear, too much backlash occurs, the traversing screw and nut must be replaced. The flange F is secured by 2 taper pins.

Blatt

Individual drive TV-45

INDIVIDUAL DRIVE TV-45. No.	408-419,	Works no.:
The headstock is driven ho	rizotally from the indiv	idual drive TV-45.
Built within this are the	motor and also the tooth	ed-wheel reduction gear
(1:6). The latter is actua	ted by means of the lewe	r on the casing. With the
lewer in the middle positi	on, the gear remains dise	ngaged.(Idling position).
The shifting operation may	be facilitated, if neces	sary, by a light pull on the
headstock driving belt. The	gear may only be shifte	d when at rest. The tightness of
headstock driving belt can	be finely regulated as	desired by means of the
tightening screw. The rapi	d tightening lever in th	e baseplate serves for changing
the belt quickly from one	step to another, as well	as for relieving the belt pull.
The tightness of the belt	between motor and gearin	ig can be re-adjusted at the
upper pulley (gearing).By	loosening the thereaded	pins and simultaneously
adjusting the countersunk	screws (as uniformly as	possible along the whole periphe
the V-belt can be tightene	d or loosened.	
As gear oil, we recommend	the following makes:	
(In alphabetical order)		
Caltex Qil	Regal AZ	2.9°E at 50° C
Esso Standard	Teresso 43	2.8°E at 50° C
Shell	Vitrea 27.	3° E at 50° C
Vacuum Oil (Mobil Oil)	DTE light	2.8°E at 50° C
When working 8 hours daily	, the ball bearings of th	ne motor should be thoroughly
cleaned once every 2 years	and provided with fresh	grease.
Initial speeds of the indi	vidual drive:	
V-belt: Motor/Gearing	profile 13 x 8 mm, inner	r length mm
Flat belt: Individual dr	ive/Headstock: profile 1	13 x 3 mm, inner length 1140 mm
V-belt: Individual dr	ive/Headstock: profile]	13 x 8 mm, inner length 1120 mm
Motor for 240 switchings p	er hour.	
M-4 (4), (-4,1, -1-2,		
Motor no individual drive		
Motor no coolant pump		

Bellagen, die dem Empfänger anvertraut sind, verbieibt jederzeit unserer Firma. Ohne unsere schriftliche Genehmigung dürfen sie weder kopiert noch vervielfältigt, auch niemals dritten Personen mitgeteilt oder zugänglich gemacht werden.


SIMONET & CO. A.G. SOLOTHURN SCHWEIZ

Geschr. 4.11.64 Hug Gepr. PD-50-102 8 latt Nr. 8

Bench lathes DC-102 DR-102 DD-102 DZ-450


Wiring diagram


Motor with two speeds for rotating in either direction.



Motor	Voltage	220/240 V	380/420V	500 V
1500/3000r.p.m.	Rated current	2,4/3,2A	1,4/1,85A	1,1 /1,4A
0,75/1,1HP	Motor protection	2,4/3,75A	1,6/2,5A	1,2/1,86A

Wiring point without motor protection





Hand switch H4 B6.41.004

Leading-out wire Motor 3000 r.p.m.

Tag board Motor

W

Leading-out wire Motor 1500 r.p.m.

Beilagen, die dem Empfanger anvertraut sind, verbleibt jederzeit unserer Firma. Ohne unsere schriftliche Genehmigung durfen sie weder kopiert noch vervielfältigt, auch niemals dritten Personen mitgeteilt oder zugänglich gemacht werden.

SIMONET & CO. A. G. SOLOTHURN SCHWEIZ

Geschr. 12.1.72 % Nr. PD-50-105

SCREW CUTTING AND AUTOMATIC LONGITUDINAL FEED

First of all, make sure that the clamping eccentric 12 under the cross slide is loosened; this eccentric clamps the slide to the bed during transverse turning. After removing the collet tube and the protecting cover, the change wheels are accessible. According to the change-wheels table which is provided inside the protecting cover (see also sheets 13 and 14), the desired pitch of thread or feed can be selected. The change wheels are fixed, according to the given diagram, on the change-wheel bolts and quadrant or on the lead screw respectively. The fine-feed gear (1:4) can be engaged or disengaged by the handle 4. By changing-over the lathe-dog lever 1, the lead screw is engaged or disengaged, or its direction of rotation is changed with respect to the direction of rotation of the headstock spindle. (Lefthand thread or change of direction of feed). The lead screw has a groove along its whole length and serves at the same time as feed shaft. The longitudinal feed thus imparted by the apron to the cross slide amounts to about 1/3 of the pitch of thread producted by the change wheels.

For thread cutting, the engaging lever 10 must be pushed to the back and held in a notch.

The levers of the fine-feed gear 4 and of the lathe dog 1 may only be moved when the lathe is at rest. The shifting operation may be facilitated by pulling the flat belt.

Any play that develops in the longitudinal guides of the cross slide can be eliminated by re-adjusting the two wedge-shaped rails.

SIMONET & CO. A.G. SOLOTHURN

SCHWEIZ

Geschr. 25.5.56 2-Gepr.

Nr. PD-50-107

Sheet No.

THE APRON


This transmits the movements of the combined lead screw and feed shaft to the cross slide.


Longitudinal turning:

When the lever 10 is drawn to the front, the longitudinal feed is engaged. It can be disconnected at any time by pulling the disconnecting knob 9 out, quickly and energetically.

Automatic disconnecting device

Two stops 2, clamped with holders 3, are provided, one on each side of the apron. The disconnecting rail 5 runs onto the stops to the left or to the right and disconnects the operations of longitudinal turning or thread cutting. The stop screw 6 serves as fixed stop during longitudinal turning. In order to ensure correct automatic disconnecting, at the moment of disconnecting there must always be a clearance of at least 0.01" between stop screw and stop contact. After the disconnecting, the slide is moved to the fixed stop 6 with the handwheel 8. In this way the turned length always remains unchanged. The stop screw 6, however may not be used for adjusting the turned lengths.





SIMONET & CO. A.G. SOLOTHURN

SCHWEIZ

Geschr. 2.3.60 11. Gepr.

PD-50-108

Blaff Nr.

Thread cutting:


When lever 10 is pressed to the back, the split nut is closed. In order to reduce wear, this should only be done when the lead screw is at rest; the correct position is found by moving the handwheel 8.

Because of this single-lever operating, errors in gear shifting are rendered impossible.

Also this movement can be interrupted by pulling the knob 9 out. This pulling must be done quickly and energetically. When thread cutting, the return is made by reversing the sense of rotation of the motor.

OVERLOADING THE APRON

In order to prevent breakage or deformation when the apron is overloaded by mounting-up, etc., the change wheel D is coupled to the lead screw as shown in the sketch below. If the feed is brought to a standstill by an external force during longitudinal turning or thread cutting, and the motion still remains engaged, the brass pin will shear (Safety shearing device).



Only ORIGINAL shearing pins may be used



SIMONET & CO. A.G.

SCHWEIZ

Geschr. 2.3.60 Ull. Gepr.

Blatt Nr. PD-50-131

METRIC	PITCHE	S				ENGL	SH PITC	HES			
Thread pitch A.C Pitch in mm in mm with B.C 3				Threads per A.C. $=$ 25.4 inch with B.D $=$ 3 x threat per inch					reads		
Lever	pos.	Cha	ange	whee	els	Lever	pos.	Cha	inge	whee	els
I	II	A	В	C	D	I	. II	A	В	C	D
0.2	0.05	36	120	28	126 _	- 28	112	36	120	127	126
0.25	0.06	36	108	30	120	24	96	36	108	127	120
0.3	0.07	36	90	30	120	22	88	36	108	127	110
0,35	0.08	36	80	28	108	20	80	36	100	127	108
0.4*	0.1*	36	70	28	108	19	76	36	95	127	108
0,45	0.11	36	108	54	120	18	.72	36	90	127	108
0.5	0.12	36	54	30	120	16	64	36	108	127	80
0.6	0.15	36	100	70	126	14	56	36	108	127	70
0.7	0.17	36	100	70	108	12	48	36	120	127	54
0.75	0.18	36	108	90	120	11	44	36	110	127	54
0.8	0.2	36	100	80	108	10	40	36	100	127	54
0.9	0.22	36	100	90	108	9	36	36	90	127	54
1	0.25	36	90	100	120	8	32	36	80	127	54
1.25	0.31	36	80	100	108	7	28	36	70	127	54
1.5*	0.37*	36	80	120	108	6	24	36	1.08	127	30
1.75	0.43	36	54	70	80	5	20	36	90	127	30
2	0.5	36	108	150	60						
2.5	0.62	36	54	100	80						
3	0.75	36	54	120	80		0			A=3	6
3.5	0.87	36	60	105	54 .	1911	/ ()=	1	1	
4	1	36	108	120	30	/	7	$\gamma(\cdot)$	1	I	-
						1/	$\hat{\Omega}$.	O	20	1	—II
			\ \				11 /	X	1	1	1
	able ch	F- 1402V					d		-ET	+	<u></u>

FEEDS

The longitudinal feed amounts to about 1/3 of the thread pitch. The thread pitches marked with an asterisk (*) give suitable feeds of approximately 0.13-0.03 mm and 0.5-0.12 mm per rev. respectively.



Geschr. 25.5.56 🎜 🖟

PD-50-109

Nr.

Sheet No.


	itish	reads	BoAo	0	13	3 /	47°3	0'/	A	, A		-		
122111	Assoc	th		•			70	//	42		8	7		
Addition change w									56					
Pitch error mm		-0°0002	-0,0011	-0.0002	-0.0017	+0,0008	+0.0107	+0.0025		-0.0007	-0.0054	900000-		
	D	120	105	100	110	126	126	105	126	126	120	108		
wheels	C	100	110	90	80	54	70	28	99	54	30	28		
	В	90	126	120	108	70	100	54	100	108	70	80		
Change	А	36	36	.98	36	36	36	36	36	36	92	36		
Pitch in mm	P	1,000	0.899	0.810	0.729	099°0	0.589	0.531	0.480	0.429	0.391	0.350		
		0072	.0064	.0058	,0052	.0047	,0042	.0038	.0034	.0031	,0028	,0025	× *	
es	D	,0236	,0212	.0191	.0172	,0156	.0139	.0125	.0113	.0101	.0092	.0083		
in inches	4	.0394	.0354	.0319	.0287	.0260	.0232	.0209	.0189	.0169	.0154	.0138		
	В.	.1890	.1663	.1463	.1272	11105	0860°	,0852	.0758	,0664	,0564	.0503		
Dimensions	4	.2362	.2087	.1850	,1614	.1417	,1260	.1102	,0984	9980°	.0748	6990°		
	Threads per inch	25,38	28,25	31.35	34,84	38.46	43,10	47.85	52.91	59,17	64.94	72.46		
	No.	0	+	N	m	*0"	in	9	7	0	0	10		

SIMONET & CO. A.G. SOLOTHURN

SCHWEIZ

Geschr. 25.5.56 25 Gepr.

Nr. PD-50-110 Sheet No.



vervielfaltigt, auch niemals dritten Pers geteilt oder zuganglich gemacht werden


SIMONET & CO. A. G. SOLOTHURN SCHWEIZ


Gepr

5.7.71 XJally

Blatt Nr.

PD-50-111





Lubricating plan

- Lubricating oil 3.5 4.5 ≥ E at 50 ≥ C
- Lubricating oil according to working instructions Sheets No. 3 and 8



SIMONET & CO. A.G.

SOLOTHURN SCHWEIZ

21 4 65 Gest Cepr

PD-50-112

Sheet No 16

Height of centres: 102 Distance between centres: 450 mm

Works number:

Measuring operation	Admis, error	Error found	Fig.
BED Bed straight in longitudinal direction (Only upwards curvature admissible	0 mm + 0.02 mm		18
Bed straight in the transverse direction	t or - 0.02		16
Contre running true	O.Cl me		2a .
Spindle nese, running true	0.005 mm		26
Inner cone for collet, running true	0.01 mm		200
Antal play of spindle	0.01 mm		2d
Radial deflection of spindle bearing measured at the end of an arbor at 200 mm distance	Q.01 mm		. 3a
Spindle axis parallel to the bed in the vertical plane at 200 mm	0 + 0.01 mg		4a 4b
tool pressure)	0 + 0.01 mm		4c 4d
OMPOUND SLIDE REST Sper part of slide rest longitudinal guiding parallel to spindle in vertical plane (measured at along slide movement)	0.02 mm		5
AILSTOCK Spindle sleeve parallel to the bed in vertical direction, seasured on sleeve travel (only rising to the front end)	0 + 0.01 am		5a 6b
the same in horizontal direction (Error only admissible towards tool pressure)	0 + 0.01 mm		6c 6d
centre line parallel to the bed in vertical direction, measu- red with 300 nm long testing arbor between the centres	0 + 0.01 mm		7a
he same in horizontal direction. (Error only admissible towards tool pressure).	0 + 0.01 mm		76
EAD SCREE	± 0.03 mm		4
engitudinal play of the lead scree	0.01 mm	-	8
carings of lead screw in alignment with each other in the certical plane (Bearing exes parallel to bed guide). Test positions 8 and C.	0.1 mm		88
he same in the herizontal plane	O.F an		86
learings of lead scres in alignment with split nut in the ver- lical plane. Weasured with closed spelit nut, and test position as starting point.	0.15 mm		8c
athe turns circular	0.005 mm		
athe turns cylindrical on 300 mm	0.01 mm		
athe turns fecing (only hellow) to 200 mm diameter	0.01 mm		9

Countersigned by:

Reparks:

The lathe has been tested with the belt normally tight

For the figures see sheet No. 16



SIMONET & CO. A.G.

SOLOTHURN


SCHWEIZ

Geschr. 25.5.50 77 Gepr.

Nr.

Sheet No.

PD-50-118



Beiltagen, die dem Empfänger anvebleibt jederzeit unserer Firma. Ohr liche Genehmigung dürfen sie werwielfältigt, auch niemals dritter geteilt oder zugänglich gemacht v